



GIBLI NEW MENU
From Software V201

Address	Address	DMX address:001-XXX :	
Mode	User Mode	Stand Mode Basic Mode Extend Mode User Mode A User Mode B User Mode C	
	Edit User ModeA :	Max channel PAN :	
Options	Status	No DMX Mode Pan Reverse Tilt Reverse Pan Degree Feedback Init PAN Init TILT Pan/Tilt Spd Zoom/Focus Spd Jog Wheel Hibernation Ethernet to DMX	Close/Hold/Auto ON/OFF ON/OFF 630/540 ON/OFF ON/OFF ON/OFF ON/OFF Speed 1~ 4 Speed 1~ 3 Sensitivity1 / Sensitivity2 OFF , 01M~99M ON/OFF
	Service PIN	Service PIN Set Ip Set Mask Ip Cross Load SW Clr LED Timer Clr Error Info	Password=XXX xxx.xxx.xxx.xxx xxx.xxx.xxx.xxx ON/OFF ON/OFF ON/OFF
	Fans Control	Fans Speed	Auto Stage Silence Super Silence
		Constant Fans	ON/OFF

	Disp.Setting	Shutoff Time Flip Display Key Lock DispFlash	02~60m 05m ON/OFF ON/OFF ON/OFF
	Signal Select	DMX WDMX Art—Net sACN	
	Temp. C/F	Celsius Fahrenheit	
	Initial Pos.	PAN =XXX	
	Wireless DMX	Activate WDMX Act&Data Out Rest WDMX	
	Dim Curve	Square Law Linear	
	Refresh Select	1.2K 2.4K 16K 25K	
	Gobo Correction	ON/OFF	
	Reset P/T Fade	ON/OFF	
	Trigger	DMX Value Disp. Set To Slave Auto Program	PAN..... Slave1,Slave2,Slave3 Master / Alone
	ResetDefault	ON/OFF	
Info	Time Info.	Current Time Ttl Life Hrs Last Run Hrs LED Hours Timer PIN Clr Last Run	
	Temp. Info	Head Temp.	
	Fan Info.	xxxxRPM	
	Software Ver	V1.0.....	
	Network	IP,Mask,Mac	
	Error Info.	Error Record 1 :	
Test	Home	All Pan&Tilt Color Gobo Other	
	Test Channel	PAN	

	Manual Ctrl.	PAN =XXX :	
	Calibration	-Password- PAN :	
	Gobo Replace	RotGobo Wheel FixGobo Wheel	
Preset	Select Prog.	Prog. Part 1 = Program 1 ~ 10 Program 1 Prog. Part 2 = Program 1 ~ 10 Program 2 Prog. Part 3 = Program 1 ~ 10 Program 3	
	Edit Prog.	Program 1 : Program 10	Program Test Step 01=SCxxx Step 64=SCxxx
	Edit Scenes	Edit Scene 001 ~ Edit Scene 250	Pan,Tilt,..... --Fade Time-- --Scene Time-- Input By Outside
	Scenes Input	XX~XX	